

Visy Pulp and Paper Tumut CEMS - Exceedance Report

22/06/2020

Reporting Period: 1/05/2020 - 1/06/2020 Environment Protection Licence No: 10232

Main Stack 1

Monitoring Location No: 1
 Monitoring Type: Continuous
 Sample Type: Air
 Description: Exit point from Stack 1 to atmosphere

Hydrogen Chloride (HCl)		Period: 60 Minutes	Limit: 50.00 mg/Nm3			
Start Time	End Time	Cause	Operational State	Explanation	Corrective Action	Max Reading
21/05/20 15:00	21/05/20 17:00	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		1,000.00
21/05/20 17:00	21/05/20 19:00	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		1,000.00

Nitrogen Oxides (as NO2)		Period: 60 Minutes	Limit: 400.00 mg/Nm3			
Start Time	End Time	Cause	Operational State	Explanation	Corrective Action	Max Reading
21/05/20 16:00	21/05/20 17:00	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		910.19
21/05/20 17:00	21/05/20 19:00	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		908.86

Opacity		Period: 6 Minutes	Limit: 20.00 %			
Start Time	End Time	Cause	Operational State	Explanation	Corrective Action	Max Reading
27/05/20 08:12	27/05/20 08:24	Lime Kiln B	Lime Kiln A Un Scheduled Start-up/Shut-down	Shut down LK B - no condensate for LMDF	Wait for condensate supply to be resolved and restart.	40.00

Main Stack 2

Monitoring Location No: 22

Monitoring Type Continuous

Sample Type: Air

Description: Exit point from Stack 2 to atmosphere

Opacity		Period: 6 Minutes	Limit: 20.00 %			
Start Time	End Time	Cause	Operational State	Explanation	Corrective Action	Max Reading
01/05/20 17:06	01/05/20 17:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	25.31
02/05/20 17:06	02/05/20 17:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	25.18
03/05/20 17:06	03/05/20 17:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	25.50
04/05/20 17:06	04/05/20 17:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	25.46
05/05/20 17:06	05/05/20 17:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	26.25
06/05/20 17:06	06/05/20 17:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	27.11
07/05/20 17:06	07/05/20 17:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	26.65
08/05/20 17:06	08/05/20 17:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	26.75
09/05/20 17:06	09/05/20 17:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	23.88
10/05/20 17:06	10/05/20 17:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	20.78
14/05/20 07:06	14/05/20 07:12	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		21.90
14/05/20 07:48	14/05/20 07:54	Recovery Boiler B	RB B Un Scheduled Start-up/Shut-down	Stopped BL firing - no HBL due to issues in Digester	Wait for HBL supply and restart the Rec Boiler HBL firing.	25.32
14/05/20 08:00	14/05/20 08:48	Recovery Boiler B	RB B Un Scheduled Start-up/Shut-down	Stopped BL firing - no HBL due to issues in Digester	Wait for HBL supply and restart the Rec Boiler HBL firing.	31.58
14/05/20 08:54	14/05/20 09:00	Recovery Boiler B	RB B Un Scheduled Start-up/Shut-down	Stopped BL firing - no HBL due to issues in Digester	Wait for HBL supply and restart the Rec Boiler HBL firing.	22.58
14/05/20 09:06	14/05/20 09:12	Recovery Boiler B	RB B Un Scheduled Start-up/Shut-down	Stopped BL firing - no HBL due to issues in Digester	Wait for HBL supply and restart the Rec Boiler HBL firing.	21.23
14/05/20 10:24	14/05/20 10:30	Recovery Boiler B	RB B Un Scheduled Start-up/Shut-down	Stopped BL firing - no HBL due to issues in Digester	Wait for HBL supply and restart the Rec Boiler HBL firing.	30.67
15/05/20 07:06	15/05/20 07:12	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		21.83
16/05/20 07:06	16/05/20 07:12	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		23.20
17/05/20 07:06	17/05/20 07:12	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		23.51
18/05/20 07:06	18/05/20 07:12	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		24.64
19/05/20 07:06	19/05/20 07:12	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		23.95

19/05/20 09:30	19/05/20 09:54	Recovery Boiler B	RB B Un Scheduled Start-up/Shut-down	Mill Power Black out	Restart the Boiler after the power returns	55.09
20/05/20 09:30	20/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		21.62
21/05/20 09:30	21/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		22.08
22/05/20 09:30	22/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		22.21
23/05/20 09:30	23/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		23.88
24/05/20 09:30	24/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		24.61
25/05/20 09:30	25/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		23.78
26/05/20 09:30	26/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		25.55
27/05/20 09:30	27/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		23.89
28/05/20 09:30	28/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		24.43
29/05/20 09:30	29/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		26.40
30/05/20 09:30	30/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		27.15
31/05/20 09:30	31/05/20 09:36	Auto Zero Span Verification	Normal (Steady State)	Auto calibration		27.31

Authorised By:

Uday Bhagwat
Pulp Mill Manager



Johan Stoltz
General Manager

