

Visy Pulp and Paper Tumut CEMS - Correction Log

18/10/2020

Reporting Period:

1/09/2020 - 1/10/2020

Environment Protection Licence No:

10232

Main Stack 1

Monitoring Location No:

1

Monitoring Type

Continuous

Sample Type:

Air

Description:

Exit point from Stack 1 to atmosphere

Opacity					
Period: 6 Minutes		Limit: 20.00 %			
Start Time	End Time	Cause	Operational State	Explanation	Max Reading
03/09/20 14:18	03/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.67
04/09/20 14:18	04/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.83
05/09/20 14:18	05/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.01
06/09/20 14:18	06/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.94
07/09/20 14:18	07/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.13
08/09/20 14:18	08/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.14
09/09/20 14:18	09/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.27
10/09/20 14:18	10/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.44
11/09/20 14:18	11/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.84
12/09/20 14:18	12/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.04
13/09/20 14:18	13/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.02
14/09/20 14:18	14/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.34
15/09/20 14:18	15/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.62
16/09/20 14:18	16/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.01
17/09/20 14:18	17/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.21
18/09/20 14:18	18/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.02
19/09/20 14:18	19/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.21
20/09/20 14:18	20/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.14
21/09/20 14:18	21/09/20 14:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.27
26/09/20 14:12	26/09/20 14:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.01

27/09/20 14:12	27/09/20 14:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.73
28/09/20 14:12	28/09/20 14:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.78
29/09/20 14:12	29/09/20 14:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.09
30/09/20 14:12	30/09/20 14:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.18

Main Stack 2

Monitoring Location No: 22
Monitoring Type: Continuous
Sample Type: Air
Description: Exit point from Stack 2 to atmosphere

TRS (as H2S)		Period: 60 Minutes	Limit: 3.60 mg/Nm3		
Start Time	End Time	Cause	Operational State	Explanation	Max Reading
04/09/20 12:00	04/09/20 14:00	Instrument Error	Normal (Steady State)	Friday Maintenance carried out.	16.03
10/09/20 10:00	10/09/20 11:00	Instrument Error	Normal (Steady State)	Weekly Maintenance done on unit a day early	5.50
18/09/20 09:00	18/09/20 12:00	Instrument Error	Normal (Steady State)	Weekly Maintenance	16.49
25/09/20 09:00	25/09/20 11:00	Instrument Error	Normal (Steady State)	Weekly Maintenance on CEMS unit	15.39

Authorised By:

Uday Bhagwat
 Pulp Mill Manager

Johan Stoltz
 General Manager


 26.10.2020


 26/10/2020