

Visy Pulp and Paper Tumut CEMS - Correction Log

7/07/2020

Reporting Period:

1/06/2020 - 1/07/2020

Environment Protection Licence No:

10232

Main Stack 1

Monitoring Location No:

1

Monitoring Type

Continuous

Sample Type:

Air

Description:

Exit point from Stack 1 to atmosphere

Opacity					
Period: 6 Minutes		Limit: 20.00 %			
Start Time	End Time	Cause	Operational State	Explanation	Max Reading
01/06/20 14:42	01/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.96
02/06/20 14:42	02/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.13
03/06/20 14:42	03/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.58
04/06/20 14:42	04/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.10
05/06/20 14:42	05/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.13
06/06/20 14:42	06/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.14
07/06/20 14:42	07/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.79
08/06/20 14:42	08/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.78
09/06/20 14:42	09/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.19
10/06/20 14:42	10/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.18
11/06/20 14:42	11/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	24.27
12/06/20 14:42	12/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.90
13/06/20 14:42	13/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	24.50
14/06/20 14:42	14/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	24.98
15/06/20 14:42	15/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	25.56
16/06/20 14:42	16/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	25.90
17/06/20 14:42	17/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	24.03
18/06/20 14:42	18/06/20 14:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.07
24/06/20 14:36	24/06/20 14:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.62
25/06/20 14:36	25/06/20 14:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.02

26/06/20 14:36	26/06/20 14:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.35
27/06/20 14:36	27/06/20 14:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.76
28/06/20 14:36	28/06/20 14:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.13
29/06/20 14:36	29/06/20 14:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.01
30/06/20 14:36	30/06/20 14:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.68

Main Stack 2

Monitoring Location No: 22

Monitoring Type Continuous

Sample Type: Air

Description: Exit point from Stack 2 to atmosphere

TRS (as H2S)		Period: 60 Minutes	Limit: 3.60 mg/Nm3		
Start Time	End Time	Cause	Operational State	Explanation	Max Reading
07/06/20 02:00	07/06/20 03:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	4.81
21/06/20 02:00	21/06/20 03:00	Recovery Boiler B	Normal (Steady State)	Auto Calibration	8.51
28/06/20 02:00	28/06/20 03:00	Recovery Boiler B	Normal (Steady State)	Auto Calibration	8.88

Authorised By:

Uday Bhagwat
Pulp Mill Manager



Johan Stoltz
General Manager

